

EXCAVATED MATERIAL - STOCKPILE AREA IS TOO CLOSE TO OPEN EXCAVATION. MIN. DISTANCE IS REQUIRED TO PREVENT EXTRA WEIGHT OF EXCAVATED MATERIAL FROM CAUSING CAVE-IN

WORK ZONE SIGNS ARE REQUIRED ... EVEN IF "NO WORK" IS OCCURING. WSDOT & CITY OF SHELTON REQUIREMENTS WERE NOT ADHERED TO.

SAFETY VIOLATION - INADEQUATE SIGNS / CONES . CAUTION TAPE ALONG OPEN EXCAVATION.

EXCAVATION DEPTH EXCEEDED 4 FT. OSHA REGS. REQUIRES A METHOD OF INGRESS / EGRESS (E.G., LADDER, ETC.) ARE REQUIRED FOR WORKER SAFETY

EXCAVATION DEPTH EXCEEDED 4 FT. THEREFORE, SHORING PROTECTION AND / OR BENCHING ARE REQUIRED PER OSHA REGULATIONS

EXCAVATION UNDERMINED EXISTING ALLEY ... CREATING UNSAFE CONDITION FOR VEHICLES / PEDESTRIANS / WORKERS

